

INFORMATIONS DE SÉCURITÉ SUR LES SVHC

ARTICLE 33 DU RÈGLEMENT REACH – INFORMATIONS SUR LES SUBSTANCES EXTRÊMEMENT PRÉOCCUPANTES

Cher(ère) client(e),

L'objectif de l'article 33(1) du Règlement REACH (CE) n° 1907/2006 est de permettre aux clients acquérant les produits fournis de prendre des mesures de gestion des risques adéquates en cas de présence dans certains articles de substances extrêmement préoccupantes (SVHC) répertoriées dans la liste actuelle des substances candidates à l'autorisation, afin de garantir leur utilisation en toute sécurité.

FORD soutient les principes fondamentaux du Règlement REACH et plus précisément ceux énoncés dans l'article 33(1), car ils sont en adéquation avec notre propre engagement en faveur d'une fabrication, d'une manipulation et d'une utilisation responsables de nos produits.

Identification des SVHC

D'après les informations communiquées par notre chaîne logistique et les données que nous possédons sur nos produits, les SVHC présentes dans nos articles dans une concentration supérieure à 0,1 % masse/masse (w/w) sont, à notre connaissance, celles indiquées dans la « Liste des SVHC » correspondant à chaque pièce/véhicule spécifique.

Informations de sécurité spécifiques aux articles contenant des SVHC

Le cas échéant, des informations de sécurité spécifiques aux articles contenant des SVHC sont ajoutées à la « Liste des SVHC » correspondant à chaque pièce ou véhicule spécifique.

Informations de sécurité générales applicables aux articles

Chaque véhicule FORD est fourni avec un manuel du propriétaire, qui inclut des informations de sécurité à l'intention des propriétaires/utilisateurs du véhicule. Les informations communiquées par FORD sur la réparation et l'entretien des véhicules et des pièces d'origine comprennent également des informations de sécurité destinées au personnel d'entretien.

Si elles sont présentes dans des pièces de ce véhicule, les SVHC répertoriées dans la « Liste des SVHC » correspondant à chaque pièce/ véhicule spécifique sont incorporées de sorte à limiter l'exposition potentielle des clients. Tout risque pour l'être humain ou l'environnement peut être exclu tant que le véhicule et ses pièces sont utilisés conformément à l'usage prévu, et que tous les entretiens, réparations et maintenances sont effectués selon les instructions techniques spécifiées pour ces activités et les bonnes pratiques habituelles de l'industrie.

Dans l'Union européenne, le traitement des véhicules hors d'usage peut s'opérer uniquement dans une installation de traitement autorisée. Les pièces des véhicules doivent être traitées conformément à la législation locale applicable et aux directives des autorités locales.

Modèle : Ford Explorer

Liste des SVHC basée sur la liste des substances candidates de l'ECHA datée du 1er janvier 2026

Informations de sécurité spécifiques aux articles contenant des SVHC

Aucune information de sécurité spécifique n'est requise – Suivre les Informations de sécurité générales applicables aux articles.

Commodity	REACH SVHCs
Accessories	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
Air Induction	Lead [7439-92-1]
Appliques (Pillar, Decklid, Roof)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
Auto Transmission	Boric acid [10043-35-3]
	Lead [7439-92-1]
Auto Transmission Cooler and Lines	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Auto Transmission Shifter	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Body and Security Electronics	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	1-Propanol, 2,3-dibromo- [96-13-9]
	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Boric acid [10043-35-3]
	Lead [7439-92-1]
	Melamine [108-78-1]
	TBBA [79-94-7]
Body Side Interior Trim (Hard Trim)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]

	Melamine [108-78-1]
Body Structure - Floor Pan - Rear Floor	C,C'-azodi(formamide) [123-77-3]
Body Structure - Front Fender	Dicyclohexyl-phthalate [84-61-7]
Brakes	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Dicyclohexyl-phthalate [84-61-7]
	Lead [7439-92-1]
Bumpers and Spoilers	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	TBBA [79-94-7]
Climate	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Cobalt-dinitrate [10141-05-6]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Tris(nonylphenyl)phosphite [26523-78-4]
Closures and Lids BIW	Lead [7439-92-1]
Closures and Lids Mechanisms	Octamethylcyclotetrasiloxane [556-67-2]
	Triphenyl-phosphate [115-86-6]
Console Floor/Rear	Lead [7439-92-1]
Cooling	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Lead [7439-92-1]
Dressed Engine	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Driveline	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Driveline (Powerpack)	Boric acid [10043-35-3]
Driver Controls	Lead [7439-92-1]
EDS	Boric acid [10043-35-3]
	Decamethylcyclopentasiloxane [541-02-6]
	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
	Tris(2-methoxyethoxy)vinylsilane [1067-53-4]
Exhaust Cold End	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
Exterior Lighting	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
	TBBA [79-94-7]
Fascia Grille - Radiator	Lead [7439-92-1]
Front / Rear Door Trim	Cobalt-sulfate-heptahydrate [10026-24-1]

	Lead [7439-92-1]
Fuel	Lead [7439-92-1]
Glass Runs and Belts	Bumetrizole [3896-11-5]
	Lead [7439-92-1]
GOR and Radiator Support	Lead [7439-92-1]
Headliner / Sunvisor	Hexahydromethylphthalic-anhydride [25550-51-0]
Hybrid Technology	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
Interior Trim	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
	Tris(nonylphenyl)phosphite [26523-78-4]
IP and Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
IP Finish Panels/Registers	Lead [7439-92-1]
IP Substrate and Ducts	Lead [7439-92-1]
Latches - Hood, Decklid and Liftgate Latches	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Lower Body Structure	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	C,C'-azodi(formamide) [123-77-3]
Luggage and Interior Cargo Management/Covers	Lead [7439-92-1]
	Triphenyl-phosphate [115-86-6]
Mirrors	Lead [7439-92-1]
Multimedia	Boric acid [10043-35-3]
	Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8]
	Lead [7439-92-1]
	Melamine [108-78-1]
	Octamethyltrisiloxane [107-51-7]
Overhead Console	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	Lead [7439-92-1]
Pedals	Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]
Power Supply	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	Cobalt(II) nitrate hexahydrate [10026-22-9]
	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Powertrain Controls and Calibration	Lead [7439-92-1]
Powertrain Mounts	1-Methyl-2-pyrrolidone [872-50-4]
	Lead [7439-92-1]
Restraint	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]

	Lead [7439-92-1]
Roof	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
Safety Electronics	1,3-Propanesultone [1120-71-4]
	Lead [7439-92-1]
	TBBA [79-94-7]
Seat Belts (Front and Rear)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Seating	Lead [7439-92-1]
	Melamine [108-78-1]
	Phenol, dimethyl-, phosphate (3:1) [25155-23-1]
	Sodium borate, decahydrate [1303-96-4]
	Triphenyl-phosphate [115-86-6]
Seats - Foam - Cut and Sew	Triphenyl-phosphate [115-86-6]
Seats - Structures	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
	Sodium borate, decahydrate [1303-96-4]
Side Door Mechanisms	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
	C,C'-azodi(formamide) [123-77-3]
	Lead [7439-92-1]
Spoiler	Lead [7439-92-1]
Static Sealing	C,C'-azodi(formamide) [123-77-3]
Steering	Lead [7439-92-1]
	O,O,O-Triphenyl phosphorothioate [597-82-0]
Suspension Frames and Mountings	Lead [7439-92-1]
Switches	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
	2-Methylimidazole [693-98-1]
	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Transmission - Auto	Lead [7439-92-1]
Upper Body Structure	C,C'-azodi(formamide) [123-77-3]
	Triphenyl-phosphate [115-86-6]
Wash-Wipe	Dodecamethylcyclohexasiloxane [540-97-6]
	Lead [7439-92-1]
Wheels Tires Jacks and Equipment	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	Lead [7439-92-1]
	Melamine [108-78-1]
Window Regulator	Lead [7439-92-1]